

M-293
111875-01

Formerly Utilized Sites Remedial Action Program (FUSRAP)

ADMINISTRATIVE RECORD

for Maywood, New Jersey



U.S. Department of Energy



Department of Energy

Oak Ridge Field Office
P.O. Box 2001
Oak Ridge, Tennessee 37831-8723

December 22, 1993

Paul A. Giardina, Chief
Radiation Branch
Environmental Protection Agency
Region II
Jacob K. Javits Federal Building
New York, NY 10278

Dear Mr. Giardina:

DOE-OWNED FUSRAP SITES - SEMIANNUAL RADON FLUX MONITORING RESULTS - SUBMITTAL TO EPA REGION II

Enclosed for your consideration are the results of radon flux monitoring conducted at the following sites in Region II being administered by the Department of Energy (DOE) under the Formerly Utilized Sites Remedial Action Program (FUSRAP): the Maywood Interim Storage Site (MISS); the Middlesex Sampling Plant (MSP); and the Niagara Falls Storage Site (NFSS). Radon flux monitoring of contaminated soil at the New Brunswick Site, originally initiated to support characterization activities, has been discontinued.

The monitoring information is being provided for your information in the spirit of the draft Memorandum of Understanding between DOE and EPA to provide data under 40 CFR Part 61, Subpart Q, of the National Emission Standards for Hazardous Air Pollutants (NESHAPs).

The enclosed data are for the interim storage piles at MSP and MISS and the waste containment structure at NFSS. The data includes the results of semiannual monitoring conducted in October and November of 1993. Results of the monitoring indicate that the sites are in compliance with the radon flux standard of 20 pCi/m²/s.

In the interest of providing the results of radon flux monitoring in as timely a manner as possible, we will continue to submit future results of each semiannual monitoring event to EPA within 60 days of each sampling event. This time period is necessary in order to consolidate the monitoring results from all three FUSRAP sites within Region II into one transmittal.

111875


Paul A. Giardina

2

December 22, 1993

If you have any questions, please contact me at (615) 576-0730.

Sincerely,



Lester K. Price, Director
Former Sites Restoration Division

Enclosure See Administrative Record Document # M-266